

Rpt. 8.

(Received at London Office 24 JUL 1947)

No. 115236A

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writ. Report... When handed in at Local Office... 19... Port of London

No. in Reg. Book. Survey held at... Date, First Survey... Last Survey... 19... (No. of Visits...)

06894 on the Wood Iron or Steel "EMPIRE BARBARA"

TONNAGE: GROSS 274 Built at Selby By whom Cochrane & Sons Ltd. When 1945 MONTH 2

UNDER DK. 226 Owners The Admiralty Owners' Address... (If not already recorded in Appendix to Register Book)

NET... Managers... Port belonging to Hull

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage...

Cell/D/Bor/D/Ba... feet; uE&B... feet; f... feet } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

total capacity... tons. FPT... tons; APT... tons; MT... feet tons. } CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys. Machinery and Boiler Surveys (Including date of N.B. if any).

N.B. All alterations in the existing records should be underlined. Last Report, No. 52761. Port Hull.

Particulars of Classification: +100 A1 For towing services 2.45 Fitted for oil fuel 2.45 2 P. above 150 FT.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Faired or Repaired								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Caulking of Decks	Cement or Asphalt	Oil Bunkers	Boats
Stowings	Rudder	Scuppers	Masts, Yards, &c.
Beams & Fastenings	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
Outside Plating	Windlass	Hatches	Equipment letter
" " in way of sidelights	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Reverse Frames	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diam. (on board.)
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Transverses	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Lecker
Floors	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Keelsons		" " at other places	Standing and Running Rigging
Stringers		Stringers, Clamps & Shelves	Sails
Inner Bottom Plating		Salting (State if examined.)	
Have the Tanks been examined internally?			
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c. :— State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19.
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19.

Committee's Minute... Character Assigned... Delete class now + all particulars on reprint



MADE AND PRINTED IN ENGLAND. (The Surveyors are required to write on or before the space for Committee's Minutes.)

Is Certificate required? If so, to be sent to

008925-008937-0114