

1 copy please



# Lloyd's Register of Shipping,

49, Queen Square,

Bristol, 18th March, 1950.

RECEIVED

20 MAR 1950

ANSD... 28/3

Dear Sir,

Barge "JOHN HARKER"

Reference

In reply to your letter of the 9th instant respecting an explosion in the engine room of the above vessel and referred to in the 73rd Annual Report of H.M. Inspector of Explosives, we have to inform you as follows :

The after bulkhead of the pump room has been renewed and has no openings into the engine room. The telegraph cables now pass from the bridge to the engine room through a pipe running through the top of the pump room, and flanged at fore and after bulkheads.

The cargo pipe branch to the pump room and master valve have been removed, and the cargo pipe terminates, and is blanked off at the forward side of the bridge.

There is therefore no possibility of a recurrence of conditions at the time of the accident in question.

Yours faithfully,

The Secretary,  
LONDON.

Lloyd's Register  
Foundation

Chief Engineer Surgeon  
Referred to ~~Mr. Perrie Cook~~

Noted  
acknowledge with thanks  
R.L.

R.L.

copy given to  
Mr. Beveridge 31/3/50



© 2020

Lloyd's Register  
Foundation