

John Harker.

submitted Copies of 73rd Annual Report of HM
Inspectors of Explosives See detained & forwarded
Hull, Manchester, Leeds, Bristol & London
the Surveyors attention be drawn to the explosion
described on page 29.

The Bristol Surveyors be asked whether any steps
were taken to isolate the Engine Room ~~at the entrance~~
~~of the telegraph gear~~ to prevent recurrence of conditions
Bro Rpt 17105.

Repl.

22/2/50.

~~11~~ D. requested RMA. 23/2/50



© 2020

Lloyd's Register
Foundation

008964-008972-0114