

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *St S JOHN HARKER* Rpt. *Jul* No. *41132*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

*1st Long*Transverse No. *840*Depth "d" *✓*Framing: Table No. *✓*Description *Bulk angle frames as appraised**2nd* Longitudinal No. *2940*Proportions $\frac{\text{Length}}{\text{Depth}} =$ *✓*~~Deck~~ Sheerstrake*as appraised**Revised Rules*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100A.1. (Steel) Carrying Petroleum in Bulk

*for Coasting service between Worcester, Swansea and Bideford
and for service between the Humber and Poole Harbour until 31st October 1930.*

10" (Stl)

DTa 3' 10", D.Tsf 5' 15", and 10' 6"

FK, Q.B.H middle line bulkhead now oiltight. pt cam, Claydon A.C.P.

TRUNK 51'.

machs apr.



© 2020

Lloyd's Register
Foundation

008964-008972-0138