

5m.10.38.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor 26 FEB 1941

VESSEL'S NAME

"SYDNEY MARU"

Rpt.

Kob

No. 11696

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to shell plating (s.s) in way of No. 1 hold below load water line being specially examined at the next dry docking.

The KOBE Surveyors report the vessel placed in dry dock, bottom coated, some defective bottom rivets overhauled and minor repairs effected.

The shell plating in way of No. 1 hold, as above, specially examined and found in good condition.

It is submitted the vessel appears worthy to remain as classed with record of survey 12.40, without special condition.

100A1
With fbd
12.40 Kob

)
) Without, etc.
)



24.2.41

Lloyd's Register
Foundation

008973-008981-0247