

2 E

Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

NAME "SYORYU" MARU Rpt. Smk. No. 2575

Marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey ~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.~~

This Survey, due 3.40 ^{now} ~~partly~~ held, survey held on engines, ~~now~~ ~~completed~~, and the following repairs carried out (due to damage through):-
propeller striking an obstruction:-

Propeller repaired.

Wear and tear:- Some combustion chamber stays renewed
and electric welding repairs effected to furnaces.

It is submitted the vessel is eligible to remain as classed, with
notation of ~~ELMC~~ 5.40, S 4.40. as recommended.



© 2021

Y. Kim
Lloyd's Register
Foundation
15.7.40

008982-008992-0086