

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SELS NAME

"LOUIS JOLLIET"

REPORT

Qbc.

No. 8130

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.

of Survey COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.

This Survey, due 5.51

~~not~~ partly held

4.50

now

completed, and the following repairs carried out (due to wear & tear):-

Screwshaft examined.

Stern bush rewooded.



© 2020

Lloyd's Register
Foundation

It is submitted the vessel is eligible to remain as classed, with

notation of

LMC 4.50

S 5.50

as recommended.

29. 6. 50.