

complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be

D. 38
SS Gms No 3-7
142

3m, 11, 37.

POSTPONED SURVEYS.

Case of the Steam Trawler "RONSO".

No. 13196 in Reg. Bk. 248/108 tons, Built 1915-11

Classed T10DA1 Stm Owners S. F. Slight
6-39 Trawler + LMC 4-35
S.S. Gms. No. 3-4-24 656-39 Port of Registry Grimsey
S.S. Gms. No. 2-35. CL 6-39

Survey Due 2nd Special Survey No. 3, due 7, 39.

In reply to enquiry the Owners state that at the moment they are unable to say when it will be possible for them to stop the vessel for the above survey to be held.

Submitted action be deferred for a short time

[Signature] *[Signature]*
28 AUG 1939

Committee's Minute TUE 29 AUG 1939

Decision Depreciated
[Signature]



© 2020

Lloyd's Register Foundation

009015-009020-0140

f assi
d nou
er, or Y.
State if
Then put
s.
s. Yards
tion, hov
State if
pment le
ors, No.
n Locker
es (State
length
(on
Rule let
ser & W
ding and
the Reg
n as cla
ai