

TELEGRAMS
"CORRUGATED
MOTHERWELL"

SPECIALTY :—CORRUGATED FURNACES.

TELEPHONE
MOTHERWELL 176

MOTHERWELL 900 (2 LINES)

THE BROOMSIDE BOILER WORKS COY LTD

CAMP ROAD,

MOTHERWELL,

LANARKSHIRE.

20th May, 1940.

To Messrs. Grayson Rollo & Clover Docks Ltd.,

Liverpool

Ref Order from N.Y.K. Line, London
ex The Boiler Furnace Co., Ltd., Our Job No. 1313


Boiler No. "HARUKA MARU",

No.	SECTION,	Length.	Internal Diameter	Thickness
2	DEIGHTON, WITH STEPHEN GOURLAY, BACK END, (Back and Front End to Template)	8' 10" (Approx)	3' 8 1/2"	21/32"

Plates by Colvilles Ltd.,

Nos 2/5998.

The Plates have been subjected to mechanical tests and the furnaces passed for workmanship and found satisfactory by Surveyor.



Lloyd's Register
Foundation

009021-009029-00946