

# REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... 19... When handed in at Local Office... 19... Port of Greenhaven Last Survey 3-4- 1950

No. in Reg. Book. 23031 Survey held at on the Wood, Iron or Steel Sk. RALOO Date, First Survey... By whom Campbelltown Sk Co Ltd When 1919 MONTH 3

TONNAGE :- Built at Campbelltown Owners Hester Bros Ltd Ldgs Co Ltd Managers Edinburgh Pembroke & Co Port belonging to Greenhaven

Cell DB or DBa feet; uE & B... feet; f... fee } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

total capacity... tons. FPT... tons; APT... tons; MT... tons. N.B. All alterations in the existing records should be underlined. Last Report, No. 56463 Port Hull

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :- Table with columns: Shell Plates, Frames, R. Frames, Floors and Bracket Floors, Beams, Inner Bottom Plates, Dk. Plates, Other Items :-

PRESENT CONDITION OF THE Table with columns: Decks, Bulkheads, Engine Room Skylights, Copper, or Y.M., Caulking of Decks, Ceiling, Coal Bunkers, Openings, Covers, &c., When fitted, Month, Year, Coamings, Cement or Asphalt, Oil Bunkers, Boats, Beams & Fastenings, Rudder, Scuppers, Masts, Yards, &c., Outside Plating, Steering gear and its connections, Cargo Hatchways, Condition, how ascertained, Frames, Windlass, Hatches, Equipment letter, Reverse Frames, Have pumps been examined and found efficient?, Planking, Anchors, No. of, Longitudinals, Have Sluice Valves been examined and found efficient?, Caulking, Treenails, Cables (State if now ranged), Transverses, Have Watertight Doors been examined and found efficient?, Breasthooks & Stemson, " length mean diamr., Floors, Have Ventilators and their Coamings been examined and found efficient?, Transoms, Pointers & Crutches, " Rule length size, Keelsons, Air and Sounding Pipes, Stringers, Doubling Plates under Sounding Pipes, Timbers of Frame at openings, " " at other places, Chain Locker, Inner Bottom Plating, Have the Tanks been examined internally?, Stringers, Clamps & Shelves, Hawser & Warps, Have the Tanks been tested?, Doubling Plates under Sounding Pipes, Salting, Standing and Running Rigging, Sails

General Observations, Opinion as to Class, Recommendation, &c. :- State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29) £ : : Fees applied for, Special Damage or Repair Fee (if any) (per Sec. 29) £ : : Received by me, Travelling Expenses (if chargeable) £ : : Second Surveyor's Fee (if any) £ : :

Committee's Minute / TUES. 16 MAY 1950 Character Assigned As now Surveyor to Lloyd's Register of Shipping. Lloyd's Register Foundation

24 MAY 1950



Is certificate required? If so, to be sent to