



LLOYD'S REGISTER  
Recd. 10 FEB. 1926  
AGE 15  
LONDON

# Lloyd's Register of Shipping,

18, Burlington Road,

Ipswich, 9<sup>th</sup> February 1926.

Dear Sir,

With reference to your letter of the 2nd instant & the enclosed report No 6480 & letter dated 30th January from the Surveyor at Plymouth regarding the tug "H. B. Hull".

I have to state that I was very much surprised to learn repairs had been found necessary, although the Surveyor in his letter of the 30th ultimo, states there was no entry in the log book of this vessel in regard to heavy weather or of any circumstances likely to cause the leakage which was occurring. I would respectfully point out that when the vessel sailed from King's Lynn, there was 7 or 8 tons of coal put on deck, & the vessel encountered heavy weather down channel, & the Captain was so unwell that he had to be taken ashore. I am therefore of the opinion that the repairs that were found necessary, were consequent of the heavy weather encountered, & extra weight of coal on deck.

The report No 6480 Plymouth is returned herewith.


Yours faithfully,  
A. E. Farmer.

The Secretary,  
London.

009021-009029-0247





Referred to the Chief Ship Surveyor.


  
10 FEB 1926

Also for Mr. S. A. Hill to note.

Also for Mr. Hill to note,

  
10-2-26

  
12/2/26





© 2021

Lloyd's Register  
Foundation