

1m, 12, 20.

EEBOARD REPORT on the s.s. "EASTVILLE"

It is submitted the Surveyor be informed that it is concluded that the double angles at top and bottom of the hatchweb plates are as approved, but he should confirm this and give the scantlings

W.B. 87.B.
28-10-25



© 2020

Lloyd's Register
Foundation

009040 - 009049 - 0328

divisions of { }

Total depth from top of statutory deck line to top