

Jan. 10, 1940.

1

21 FEB 1941

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

L'S NAME..... "DAISY"..... Report..... No.....

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

f Survey..... When due.....

This vessel has been laid up since 1936.

The 3rd S.S. No. 1 became due 8.38, and the Owners furnished the usual undertaking.


In October last, the St. John's NFL Surveyor was requested to arrange with the Owners for the vessel to be generally examined in dry dock at a reasonably early date.

The Surveyor now encloses a letter from the Owners stating the vessel will not likely be put in commission and he does not propose to make the requisite examination as the Owners do not wish to continue the class.

It is submitted the class of this vessel be withdrawn from the Register Book and three dots (...) be inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class
Insert ...

By omit
Vessel
Govt



© 2021

Lloyd's Register
Foundation

009058-009066-0162