

Ept. 8

DISCLOSED SECTION No. 109,037a No. REPORT OF SURVEY FOR REPAIRS, &c.

(Received at London Office)

No. 109,037a

Date of writing Report 19... handed in at Local Office... Port of London

No. in Reg. Book. 56627 Survey held at on the Wood, Iron or Steel Steamer "Laisy" Date, First Survey... Last Survey... 19... (No. of Visits...)

301

TONNAGE: GROSS 248 Built at Aberdeen By whom J. Guthrie Tomy & Co. When 1912 Owners Govt of Newfoundland Owners' Address... Managers Commissioners for Finance Port belonging to St. John's

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage... Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER. For Special Survey, Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.E., if any).
<u>+100 A1</u>	<u>+LMC 8-34</u>
<u>1135</u>	<u>B 7-35</u>
	<u>CL 8-34</u>
<u>AS N.E. and no 3-8-34</u>	

Report, No. 1758 Port M.F.L.

Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to be the surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be raised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters in this case.

In cases where the Surveyor has not made a special damage report he is required to state whether he has rendered his services for this purpose and to whom and why they were declined.

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? if so, by whom?

OR EXAMINATION AS PER RULE, FOR

OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—

CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Fett.)
	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
	Cement or Asphalt	Oil Bunkers	Boats
	Rudder	Scuppers	Masts, Yards, &c.
	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
	Windlass	Hatches	Equipment letter
	Have pumps been examined and found efficient?	Planking	Anchors, No. of
	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
	Have Watertight Doors been examined and found efficient?	Treenails	length mean diamr. (on board)
	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Rule length size
	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
		Stringers, Clamps & Shelves	Standing and Running Rigging
		Salting (State if examined.)	Sails

Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

10m, 3.40.—Transfer Ink. (MADE AND PAID BY SURVEYOR) (The Surveyors are requested not to write on or below the space provided for the Committee's Minute)

Survey Fee (per Section 20)	Special Damage or Repair Fee (if any) (per Sec. 20)	Travelling Expenses (if chargeable)	Second Surveyor's Fee (if any)	Fees applied for,
£	£	£	£	19
				Received by me,
				19

Committee's Minute

TUE 25 FEB 1941

Character Assigned

White hull Lloyd's

Surveyor to Lloyd's Register of Shipping. Friday 28th February 1941 Committee's decision confirmed Lloyd's Register Foundation

009058-009066-0194

Is Certificate required? If so, to be sent to