

LLOYDS REGISTER
LONDON.
RECEIVED 25 JAN 1912
AND

Time of Receipt

TELEGRAM.

N.B.—This Form must accompany any inquiry respecting this Telegram.

POST OFFICE TELEGRAPHS.

Office Stamp.

If the Receiver of an Inland Telegram doubts its accuracy, he may have it repeated on payment of half the amount paid for its transmission, any fraction of 1d. less than $\frac{1}{2}$ d. being reckoned as $\frac{1}{2}$ d.; and if it be found that there was any error in the amount paid for repetition will be refunded. Special conditions are applicable to the repetition of Foreign Telegrams.

Origin and Service Instructions.


Charges
to pay

s. d.

Handed
in at

7 17/8

Received
here at



Cults

{ Committee London
by windlass as per specification
lift twelve hundred ~~weight~~
anchor failed today to break
anchor out of ground when
being at sea in twenty
thoms. windlass as specified unsuitable
or intended work no specified
tests Towell Cults Aberdeenshire

7 cwt shockles by Rules
6 1/2 "
105 1 1/6

12 cwt shockles



© 2021

Lloyd's Register
Foundation

Chief Engineer Surgeon

Referred to the Chief Ship Surgeon.

ad
JAN 25 1912

Urgent

Engineer Commander Seed
has been informed of
This case, & it is
Submitted action be
Deferred until
receipt of further
information from
The Surgeon

ARR

25-7-12

C.F.



© 2021

Lloyd's Register
Foundation

