

ENGINEERS, BOILERMAKERS AND SHIP REPAIRERS

7m,8,34.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME "DAISY" Rpt. NFL No. 1758

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey _____

The St. John's, N.F.L. Surveyor reports the vessel placed in dry dock, bottom cleaned and EXAMINED. coated.

On account of damage through grounding two shell plates have been renewed, stem bar part renewed, repairs effected to shell, framing, floors etc.

It is submitted the vessel appears worthy to remain as classed with record of survey 11,35.

100A1
11,35 NFL



© 2021

Lloyd's Register
Foundation

Handwritten signatures and date 9.12.35

009058-009066-0225