

COPY OF AIR LETTER.

DISCLOSED
SECTION.

496-
LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, E.C.3

29th June, 1951.

Classn(S)
A H

Dear Sir,

I have received a copy of your letter of the 5th instant addressed to the Principal Surveyor, New York, respecting the Steamer "URDANETA", the contents of which are noted.

Having regard to the fact that the Owner has made no arrangements for the overdue Special, Toller and Tailshaft Surveys to be carried out, the Committee, who have had the case under consideration at their meeting today, have given instructions for the class of the ship to be expunged from the Register Book with a Red Line, indicating withdrawal of class on account of non-compliance with the Society's Rules.

I shall be glad if you will inform the Owner accordingly.

Yours faithfully,

C.C. NEW YORK.

Clerk to the
Classification Committee.

C.H. Westbury, Esq.,
CURACAO.



© 2021

Lloyd's Register
Foundation

009067-009073-0001

009067-009073-0003