

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book. Survey held at Date, First Survey Last Survey 19
(No. of Visits)

31299 on the Wood, Iron or Steel

Ottawalite

TONNAGE:-

GROSS 415

UNDER DECK 624

NET 343

Built at Haverton Hill on Tees

By whom Furness S.B. Cold

When 1930

MONTH 4

Owners Imperial Oil Ltd

Owners' Address

(if not already recorded in Appendix to Register Book)

Managers H.J. Rahlves

Port belonging to Montreal

DISCLOSED

SECTION

No. 729

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 14064 Port Mdb

Periodical surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and Repairs being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:-

Renewed

Removed and Faired or Repaired

Faired or Repaired in place

Shell Plates.

Frames.

R. Frames.

Floors.

Beams.

Str. Plates.

Dk. Plates.

Other Items:-

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessel (State if on Felt). When put on, Month
Caulking of Decks	State if Tanks now tested	Dbing. Plates under Sounding Pipes	Boats
Coamings	Bulkheads	Engine Room Skylights	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Condition, how ascertained (State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Oil Bunkers	Sails
" " in way of sidelights	Rudder	Scuppers	Equipment letter
Breasthooks	Steering gear and its connections	Cargo Hatchways	Anchors, No. of
Transoms	Windlass	Hatches	Chain Locker
Frames	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Cables (State if now ranged) length mean diam. (on board) Rule length size
Reverse Frames		Caulking ditto	Hawser & Warps
Longitudinals	Have Sluice Valves now been examined and found efficient?	Treenails ditto	Standing and Running Rigging
Transverses		Breasthooks & Stemson ditto	
Floors	Have Watertight Doors now been examined and found efficient?	Transoms Pointers, & Crutches ditto	
Keelsons		Timbers of Frame at openings ditto	
Stringers	Have Ventilators and their Coamings been examined and found efficient?	Ditto Ditto at other places ditto	
Inner Bottom Plating		Stringers, Clamps & Shells ditto	
		Salting (State if examined.) ditto	

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 20)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute

Character Assigned

FRI. 7 AUG 1936

Andrew Cass
Insert (General Committee
Thursday, 13th August, 1936
Classed by Committee's decision

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register
Foundation