

REPAIRS, OR
when will it
The vessel was reported to have sustained damage
he Macbride

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

16th May, 1951.

Dear Sirs,

Classn.
(S)

I duly received your letter of the 26th ultimo respecting the Steamer "REG 111", the contents of which are noted.

Having regard to the circumstances in this case, the Committee have now given instructions for the class of the ship to be withdrawn from the Register Book and three dots (...) inserted in lieu thereof, indicating withdrawal of class at the Owners' request.

I shall be glad if you will inform the Owners accordingly.

Yours faithfully,

The Surveyors,
HAMBURG.

© 2020
Lloyd's Register
Foundation

009139-009143-0012