

ent to Chief Surveyors.....

Received from Chief Surveyors.....

ESSEL'S NAME "KAISANIEMI" REPORT Sea. No. 3941

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.).

ature of Survey..... When due.....

This vessel was built in 1940 and classed with Germanischer Lloyd. Classification with this Society is desired by the present Owners.

First Entry Reports and some plans have been examined and the scantlings and arrangements are acceptable.

A Classification Survey has been carried out.

On account of damage due to frost, some pumps have been replaced by second hand pumps.

Some repairs have been carried out to machinery and boilers.

IT IS SUBMITTED that this vessel is eligible for the record LMC 9.51, S 7.51 (CL).

Particulars for Register Book

Double compound and LP turbine with D.R. gearing and hydraulic coupling.

14<sup>7</sup>/<sub>16</sub>" (2) x 31<sup>1</sup>/<sub>2</sub>" (2) - 31<sup>1</sup>/<sub>2</sub>"


HS 3660 sq.ft.

MN 330

2 WTB 235 lb. (Spt.225 lb.) F.D.

Screwshaft with continuous liner.

CDM  
12. 2. 52.



© 2020

Lloyd's Register Foundation

009139-009143-0169