

S.S. 'EMPIRE CONSEQUENCE'

IT IS SUBMITTED Messrs. Shipping & Coal Co. Ltd. be informed it is noted there is no evaporator on the above ship and it is considered that, if scale is allowed to accumulate in the boiler tubes, the extra thickness would not, in any case, materially increase the life of the tubes.

W. J. F. Reel

13th September, 1946.

*See endorsement
18-9-46
W.J.F.*



© 2020

Lloyd's Register
Foundation

009139-009143-0178

as to the life of these tubes, which you have now accepted