

29 JUL 1946

"EMPIRE CONSEQUENCE"

Cpn. 11940

The Class is Subject to the double shut of valves of the boiler water gauges being replaced by Cocks at next boiler survey.

Four leaky water tubes at back ends of boilers now blanked off are recommended to be dealt with at Owners convenience.

IT IS SUBMITTED the vessel is eligible to remain as classed subject as recommended and as above.

Roll  
26/7/46



© 2020

Lloyd's Register  
Foundation

009139-009143-0189