

LONDON COPY.

C21491

Lloyd's Register of Shipping.



Port NEWCASTLE-on-TYNE.

30th October, 1945.

This is to Certify that

K. LITTLE, G.B. SCULLARD and A.A. DIAMENT

the undersigned Surveyor to this Society did at the request of Messrs J. Shipping & Coal Co. Ltd., survey the steamer "EMPIRE CONSEQUE" ex "FRIEDRICH BISCHOFF" (German) 1998 tons gross of London, formerly classed with Germanischer Lloyd, on the 13th August, 1945 and subsequent dates, and that the following parts of the Hull and Machinery were generally examined in dry dock and afloat, viz:-

- Bottom and side shell plating.
- Rudder and Sternframe.
- Holds, 'tween decks, bunkers, structure below boilers.
- The Peaks, machinery spaces, decks casings, ventilators, hatchways and closing appliances, general equipment, steering gear, windlass, masts and rigging.
- Propeller, screw shaft, stern bush, sea connections and outside fastenings.
- Cylinders, pistons, valves, seats; crank, thrust and tunnel shafting.
- Exhaust turbine casing, rotor, gears; air, feed, circulating, general service and ballast pumps and valves.
- Condenser under test.
- Windlass engine.
- The main boilers throughout and mountings and their safety Valves adjusted under steam to 240 lbs.
- Electric installation throughout.

and that we have transmitted to the Committee of Lloyd's Register of Shipping, London, a report stating that all repairs recommended by us have been completed to our satisfaction, and that we have recommended that she be assigned a record of "Examined L.R. 10:45; B.S. 10:45 and T.S.8:45, C.L." in the Register Book indicating that, from the parts seen, she appears to be in an efficient condition for a period of 12 months from October 1945.

K. Little *G.B. Scullard* *A.A. Diamant*
SURVEYORS TO LLOYD'S REGISTER OF SHIPPING.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."