

COPY

COPY.

5 - AUG 1947

Lloyd's Register of Shipping.



Port Rio de Janeiro
Rio de Janeiro
10th June, 1947.
10th June, 1947.

This is to Certify *that I have*

Surveyed the ~~Machinery~~ Machinery of the S/S "GUARAPUAVA",
Surveyed the S/S "GUARAPUAVA", 590 gross tons of Rio de Janeiro,
590 gross tons of Rio de Janeiro, on the 12th May 1947 and
on the 2nd May, 1947 and subsequently, whilst on Toc-Toc Slip-
subsequently, whilst vessel on Toc-Toc Slipway, Rio de Janeiro
way, Rio de Janeiro
and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report, stating that all repairs
and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report, stating that all repairs
recommended by me have been completed to my satisfaction, and
been carried out to my satisfaction, and that I have
that I have Recommended that she be continued as classed
Recommended that the record of Tallyhoft G.L. 5,47 &
with fresh Record of Docking 6,47
B.S. 6,47

be made in the Register Book in the case of this vessel.

being fit to carry dry and perishable cargo.

Engineer Surveyor to Lloyd's Register.


M. Catchwell

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



© 2020

Lloyd's Register Foundation