



LLOYD'S REGISTER,  
LONDON.

REC'D 10 MAR 1920  
ANS'D

*Off 42005 Owners Zeta Shipping Co*  
*(80-2 Exchange Off.)* *R Kendrick & R Evans*  
*W H Stephens Imp.*  
**Lloyd's Register of Shipping.**

18 $\frac{1}{2}$ , Regent Quay,

Aberdeen 9th March, 1920.

*how - Guarapua*

Reference

The Secretary,  
LONDON.

Sir,

With reference to your classing letter of the 5th instant respecting the case of the "Striver", Aberdeen Report No. 12394, I have to state that the intercostal in question is shown on the approved plan as formed of the lower part of the side bunker, but owing to the fineness of the ships lines it was found that at the line of bunker there was no depth of floor to fit an intercostal, and brackets were fitted from each bunker stiffener to frame in lieu of intercostals.

The boiler plan is being forwarded herewith, and I have to request that it be returned for reference during construction of a similar boiler now in hand at Messrs J. Abernethy & Coy's shop.

I am, Sir,

Your obedient Servant,

1 Enclosure.

*Boiler plan*  
*with 70-101*  
*Trawlfish*  
*(now Alcahaz)*  
*disclaves*

*W. Wilson, pro. Surveyors.*

© 2020

Lloyd's Register  
Foundation

009139-009143-0285



*Ship*  
Referred to the Chief Engineer Surveyor.

10 MAR 1920

*C.B.A.*

Boiler report checked from plan.  
plan to be returned to Abn.

*J.W.D.*  
*M* 10/3/20



© 2020

Lloyd's Register  
Foundation