

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Steel S-S. BAIKAL MARU*Rpt. *Kob*No. *1331*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *72*Depth "d" *18.7*Framing: Table No. *3*Description *Bull angle as approved*Longitudinal No. *28800*Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{13.33}{1}$ *Bridge*Deck Sheerstrake *as approved*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *100-A-1. (Steel)* "Shelter Deck" with freeboard," as recommended. The Summer freeboard of *7'-6"* from centre of disc to top of statutory deck line at *Shelter* deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

1 Dk. (Steel) & Shelter Dk. (Steel w5) 2nd Dk. (Steel) in No 1 Hold

Cell Dk 335' 792t. Tanks at Sides of Thrust Keels 8'65t FDT 37t, APT 50t

FK, 76H to Shelter Dk, 16H to Upper Dk, Cen, Av CP, B169' Fub in Shelter Dk. AH

M. 24-11-11

It is concluded the thickness of D & E Strakes of plating forward is as approved and as shown on the plan as built and not as stated; the thickness of the Shelter Deck Sheerstrake clear of the bridge is increased to 1.00" as Compensation for Side-lights and doubled at the bridge ends as approved and as shown on the plan of the vessel as built and that the amended thickness of the upper bulkhead plating has been approved but the Surveyor should be requested to state if this is so