

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

NORINA

Report Lii.

No. 113266

## For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


Nature of Survey

Condition

When due

—

Subject to stem & stem plating being dealt with at the Owners' convenience, to indented sheerstrake plating port side of engine room being dealt with & permanent repair being effected to chafed sheerstrake plating in way of port Y stbd. after gallows at the first convenient opportunity.


  
 © 23/10/39

10.39 Flt.



009200 - 009210 - 0074

 Lloyd's Register  
 Foundation