

SOUTHERN
VENTURER

MARU

M.M. 9233

WRECK
SECTION
No. 872A

WRECK
SECTION
No. 872A

RETAIN

WRECKED

J	J
F	F
M	M
A	A

M	M
JE	JE
JY	JY
A	A
S	S
O	O
N	N
D	D

WRECK
SECTION
No. 872A

(1 Bdle)



© 2020

Lloyd's Register
Foundation

009232-009234-0056 PA

SOUTHERN VENTURER MARU exSouthern Venturer-62 DF ESD GC RDR RT	14493 7096 20330	NIPPON SUISAN K.K. Japanese Tokyo	BS* Dr 10/58 whaling purposes or oil tanker—FP above 150° F. Ice strengthening MBS*	TS Whaling Factory Mchy.aft 10-1945 Furness S.B. Co. Ltd. 556' 0" 74' 5" 34' 6 1/2" LF at btm & dks	Haverton Hill 2 dks	T 6Cy. 24 1/2" 39" & 70" x 48" N.E. Mar. Eng. Co. Ltd. Wal 8 SB 220lb Spt 12 Rotary digesters 60lb 12 separators 60lb 21 PrB 70lb
---	------------------------	---	--	--	------------------------	--

NOTES											
LAIDUP-SURVEYS OVERDUE 10/62											
LAST SPECIAL SURVEY	HULL	DR 1058						MCHY.	858		
LAST DOCKING SURVEY	562										
" BOILER "	10.61										
" PRESS " AUX/DONKEY BLRS."	861										
" STM. GEN. "	/										
" SCREWSHAFT	CL P 10.60 " 9.61										
" STEAMPIPES	1058										
" WEAR DOWN ON STERN BUSH											

SS due 10.62. LAIDUP-SURVEYS OVERDUE 10/62
Press Blr 862-
MBS 10.62



© 2020

Lloyd's Register
Foundation