

Surveyors 30.7.23.

Received from Chief Surveyors

8761 90V I

NAME *Lt. S. Chippewa*

Report

ltl

No. 2103

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/03.)

Survey

When due

This vessel's class is continued subject to the main engines & the oil fuel installation being examined under working conditions & the safety valves adjusted after damage caused by fire.

The vessel was laid up at the Montreal Surveyor states that she has now proceeded to the Great Lakes.

It is submitted the Owners be asked to state what arrangements are proposed to be made to complete the survey.

AWD
1/8/23

In In. L. still
to nose & rise R. 7K.

AWD

2.8.23



© 2021

Lloyd's Register
Foundation

009243 - 009255 - 0068