

009243 - 009255 - 0071

- 9 FEB. 1923 1

by Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *StR* *bc* "Chippewa"

Rpt. *mtk*

No. 2103

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

of Survey

Damage through *fire*

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	8				6	3	9
Removed and faired or repaired.....		9			1		1
Faired or repaired in place.....							

Other items:- Casings partly renewed, deck under galley renewed, stiffeners on stokehold bulkhead removed & faired, 1 tank margin plate renewed & minor repairs effected.
Vessel examined in dry dock.


It is submitted the vessel is worthy to remain as classed with record of Survey *b.21* as recommended

100 A1

b.21 *Qbc*

Fitted for oil fuel +

It should be pointed out to the Surveyor that in all future similar cases he should state of the bottom has been examined & cleaned + coated.



Lloyd's Register
Foundation

M
Q.R. 73