

for the Engines No. 655 being constructed by *Rick* of Sheffield  
of Middlesbrough

## S.S. "Pallenzo" ex "War Relief"

It is submitted the Middlesbrough Surveyors be requested  
to state if the screw shaft is fitted with a continuous  
inner or two liners, as this is not stated in their  
report

It is concluded that 1 set of liners for adjusting block,  
bucket and rod for lubricating oil pump, 1 escape  
valve spring of each size fitted have been placed  
on board, but as these items are not included in  
the list of spare gear, the Middlesbrough Surveyors  
should be requested to state if this is so.

*W.D.*  
Lloyd's Register  
Foundation

009267-009277-0190