

009301 - 009310 - 0150

to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Stl M.V. DOLORES DE URQUIZA Report Stl No. 46022

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Signature of Survey Stl Entry. When due \_\_\_\_\_

✱ 100 A.I. (Steel) "Tram for service on the River Parana".

1 D<sup>x</sup> (Stl)

F.K, T.B.H, pt Cem pt asp, Lloyds A & CP.

*Lfbs 16/10/26*

*[Signature]*

© 2021

Lloyd's Register  
Foundation

*Stl 16.10.26*

It is concluded the thickness ~~of~~ the deck plating is as approved, but the Surveyor should be requested to state if this is so.