

16 MAR 1959

Received from Chief Ship Surveyor

S NAME "RYAD" REPORT Gen. No.23981
AR.

Standing Conditions of Class: Subject to indented shell plate J.7
(s.s. from aft) and adjacent 'H' strake plating being examined
and dealt with as necessary next S.S.

Assessment of Certificate ~~(As before)~~ or None)

Place of Present Survey: ~~(At Port and)~~ in dry dock)


Docking; Shell damage (grounding); Minor W & T repairs;

Recommendation: SUBMITTED record of 'DS 1,59' be assigned as recommended
SUBJECT as above and to buckled and indented shell plates C.8, D.3
(p.s) and C.4-11 (s.s), (all from fwd.) being specially examined
and dealt with as necessary next S.S.

DS 1,59. Subject.

AMEND THE S.R.L. APPENDIX:

Slightly wavy bottom 'B', 'C' & 'D' strakes (p.s)
Wavy & indented shell & bottom 'A', 'J' & 'L'
strakes (s.s).
(Extended S.S.).



© 2020

Lloyd's Register
Foundation

(new)

009311-009320-0115