

How. Nord has.

LLOYD'S REGISTER OF SHIPPING,  
LONDON. DOMINION BANK BUILDING

RECD 29 AUG 1919

ANSD

TORONTO

August 13th 1919.

"S"

The Secretary,  
Lloyd's Register of Shipping,  
71 Fenchurch Street.  
London, England.

Dear Sir:-

Receipt is acknowledged of your letter of the 26th  
July enclosing classification certificates covering S.S. "GENERAL  
MORRISON."

The lower part of the plating in bulkhead at frame  
No. 54 is 17.9 lbs per ft.

With reference to the joint in the screw shaft liner,  
I have to state, that the term "hard soldered" in our report does  
not refer to tinsmith solder but "silver solder" commonly used for  
the joints of bandsaws.

Under the circumstances I am returning herewith the  
clean certificate and have endorsed the Hull certificate by adding  
"and to the joint of the screw shaft liner being specially surveyed  
before the end of June 1921"

In the case of new orders in this district the builders  
are superceding the silver solder joint by a full length liner.

Yours very truly,

AS/ED.

© 2021  
Lloyd's Register  
Foundation

009321-009330-0045

BEAMS.

Angles on upper edge

Spacing

24

24

Tie Plates

Deck. Material and thickness

STEEL

No. 54



Referred to the Chief Ship Surveyor,  
and the Chief Engineer Surveyor.

*CSA*  
AUG 30 1919

Also for Mr. S. A. Hill to note.

*J. A. Wood*

*Sur.* *M*  
*30 8 19*



© 2021

Lloyd's Register  
Foundation