

COPY.

# Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

July 26th 1919

are

TORONTO

L MORRISON 125      Classed 100AI with notations Lloyd's  
and ~~MLC~~ 6.19. It is concluded that the lower part of  
ating in bulkhead frame No.54 is 17.9 lbs per foot as  
ed but I shall be glad if you will let me know if this

reference to the statement contained in your Machinery  
relating to the screw shaft liner joints, it is not quite  
what is meant by the term "Hard soldered". In the  
stances 3 certificates are enclosed, and you will be  
d as to hand the clean certificate to the Builders, in  
ent of the joint of the liner having been burned, brazed  
ctric welded, and on payment of the fees. If, however, the  
has been made with tinsmiths solder you will be so good  
hand to the builders the certificate containing the  
ement "Subject to the joint of the liner being specially  
ed before the end of June 1921."  
I be glad if you will let me know what course is adopted  
the same time return to this Office the certificate  
s not required.

s regards the certificate on the hull, you should  
ally add the Condition relating to the shafts liner joint  
event of it being necessary and advise me of the fact.



© 2021

Lloyd's Register  
Foundation

669321-009330-0016