

150,10,40. John Crown & Sons Ltd., Sunderland. Yard No. 205. F.E.

Received by Chief Ship Surveyor..... N.N. "PRESIDENT F.D. ROOSEVELT" Received from Chief Ship Surveyor.....

SEL'S NAME s.s. "GRUINARD" Rpt. sld. No. 33639

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 2250 Depth "d" -

2nd Long. No. 6375 Proportions = $\frac{L}{D}$ 10.0

Framing Angle frames as approved. Sheerstrake As approved

This steam trawler for the Admiralty is a sister vessel to the

"PETLAR", "EARRAID", "FILLA" etc.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A- "Stm Trawler" "For Government Service".

FK, 7BH,

F 27'

O.L. 164.0

E.S.D.

Note:- The bottom in way of the fresh water tank has been coated with "Bituros" and the remainder with red lead. The question of laying cement on the bottom clear of the fresh water tank, especially under the boiler, will require to be considered in the event of "For Government Service" being deleted from the vessel's class.