

cases where the Surveyor has not made a special damage report he is required to state whether he has rendered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as printed on this and any certificate

26 OCT 1927

Chief Surveyors _____

Received from Chief Surveyors _____

SHIP'S NAME "AQUAMARINE".

Report

London

No. 91934a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/192.)

of Survey _____

When due _____

The Boiler Survey became due in July last.

In reply to enquiry the Owners have informed the Buenos Aires Surveyors that they do not wish to retain the vessel in class.

IT IS SUBMITTED the vessel's class be withdrawn from the Register Book and three dots inserted in lieu indicating withdrawal of class at Owners' request.

Withdraw class.

Insert ...

22.10.27.

[Handwritten signatures and initials]



© 2021

Lloyd's Register Foundation

004321-009330-0096

Surveyor Assigned

Withdraw class to insert

vessels
red)
d)
ng
onsequ
have

Shippi