

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing.

CHARACTER.
* for Special Survey.
Date of last Survey and of

1m,2,15.

1-OCT 1919 2

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Mt. Ac. K. Aquamarine* Rpt. *Sps.* No. *82194*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


Nature of Survey

S.S. No. *2*

The *1st* S.S. No. *2* has now been held, and the following repairs done due to wear and tear:- *Vessel placed in dry dock: bottom cleaned & coated. Defective shell rivets renewed. Decks recaulked as necessary and minor repairs carried out.*

It is submitted the vessel is worthy to remain as classed, with record of Survey *9.19* and notation of *S.S. Bgs. No. 2.19* as recommended.

100 A. 1. Steamer Trawler
9.19 Bgs.
J. I. Bgs. No. 2.19.



Lloyd's Register Foundation

009321-009330-0102

Survey Fee (per Section 28)

4 : 0 : 0

Fees applied for,