

4 E

16 MAR 1950

Received by Chief Engineer Surveyor Received from Chief Engineer Surveyor

VESSEL'S NAME "HONG TAT" REPORT Sng. No. 8056

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)


Nature of Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

See previous endorsement dated 13. 10. 49 regarding this case.

MBS due 11.49 partly held, now completed.

Docking. Minor repairs effected.

IT IS SUBMITTED that this vessel is eligible for the record MBS* 7.49.



© 2020

Lloyd's Register Foundation

Handwritten signature

15. 3. 50

009331-009340-0144

Handwritten notes at the bottom of the page, including "notic of..." and "and vessel under working condition"