

S. S. PORSANGER

The process of manufacture of the hull steel is not stated in the J. E. Report.

It is, however, stated that the steel was supplied by

Illinois Steel Co. Chicago

Carnegie Steel Co. Pittsburg.

It is therefore submitted that the query be referred to the New York Office, who should cable Owners direct.

J. E. 14/10.



© 2021

Lloyd's Register
Foundation

009341-009349-0293