

POSTPONED SURVEYS.

Case of the Steel Sc.K. "AVON"

No. 0653 in Reg. Bk. 250/111 tons, Built 1907-12

Classed + 100A1 Owners St. Malo Stm. Fishing Co. Ltd.
Stm. trawler 7.22 +HMC Port of Registry Grimsby.
(G.W. Jeffs, mgr)
MS 4.23 BS 10.24
TS (4) 9.22

Survey Due 2nd Special Survey No.1 due 7,23 (Partly held).
2-years' limit on screwshaft (to examine) expired 7,24.

To complete the 2nd Special Survey No.1, the wood deck requires to be repaired as necessary, and action in the matter was deferred by the Committee in November last as the Grimsby Surveyors stated the deck had been examined and found efficient and that they were informed the necessary repairs would be effected at the vessel's annual refit in May, 1925.

On the 1st May the Grimsby Surveyors were requested to inform the Owners that the Committee considered the survey of the screwshaft and the completion of the 2nd Special Survey No.1 must receive attention by the end of June in order to entitle the vessel to retain her class.

Committee's Minute **TUES. 28 JUL 1925** P.T.O.

Decision

Exchange class with red line

*Dr Owen 28.7.25
Dr Jones*



Lloyd's Register Foundation

009350-009361-0005

General Committee
Thursday, 30th July, 1925.
Classing Committee's
decision confirmed
as



© 2021

Lloyd's Register
Foundation

POSTBOMED 2014/15/16

On the 3rd instant the Grimsby Surveyors wrote they were endeavouring to obtain a definite decision from the Owners in regard to the above matters. In the circumstances the Committee deferred action for a fortnight and the Surveyors were requested to point out to the Owners that if the necessary surveys were not taken in hand at once, the Committee would have no option but to deal with the vessel's class.

In reply to enquiry the Grimsby Surveyors write they are unable to obtain any definite information from the Owners regarding this case, and that in their opinion, no useful purpose would be served by granting any further extension of time for the completion of the Special Survey.

It is submitted the vessel's class should be expunged from the Register Book with a red line & date (—) indicating non-compliance with the Society's Rules.

Cms. WLS
27.7.25.



© 2021

Lloyd's Register
Foundation

069350-009361-0005

242