

29.6.20

Пиросцаfo № 189

Support under Mast Winlass
Winders & Steering Gear to
Increase Satisfaction

Arrangement in Green Park to
See the Exhibition

↑ This appears to be 3 yr height formerly about 2-3"

Being dead up to components for } or equivalent
Scrambling of Stiffness. } arrangements to
 } ensure satisfaction

Supp
Wine
Dun

- To begin Rule Requirements-

Parapetto collisione:
Piana 10.5
Prossima lamiera 8.
Lc oltre 7.5

[illegible]

See Sec. 22 para 12 of Rules

Doppio fondo Piano perim. laterale gnt. massiccio
e collare 25
Piano gnt. medio collare 12
Fila centrale superiore gnt. collare 1/3
Tutto il doppio fond. dipinto con "Bitumastone"

Tutte le altre mercanture come antedentemente approvate

13. Facciamo sulla parte piatta del fondo
arrà uguale grossezza che in mezzo.

Gregorio R. Q. D.^k

6" B.A. Sliff was
breached to p. Hutton

Questa lamiera è aumentata a 8 mm

3 foreafters $7\frac{1}{2}'' \times 7''$
Coperchi $2\frac{1}{2}''$

Coperata

Intercostale intermedio 2n/4
flangiata alla parte superior

R.M.M
28.6.20.

069376-00438-0018

Martinsobek h² 189
Amended Profile ^{40k}
Approved 28-6-20

G["]
s Lodolella

Tri 5140

α 9376-009386-0018



© 2021

Lloyd's Register
Foundation