

by Chief Ship Surveyor

Received from Chief Ship Surveyor

EL'S NAME *Steel S.S. "LODELETTA"*Rpt. *Yr*No. *5140.*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

First Entry

See Ltr 6-9-21
 It is Submitted before this case receives Consideration the Surveyors be requested to forward a Sketch of the bridge & fore-castle decks showing the beams and Supports, and they should be requested to State whether the flanging of the intercostals in the double bottom in the Machinery Space has been approved, and whether the scantlings of the ^{Side} Bulk Transverses and the Transverses in way of the raised Quarter Deck are as approved.

Ltr 16/8/21

© 2021

Lloyd's Register
Foundation

009376-009386-0038

Forecastle Deck, Angle, Bulb Angle, }
 Plate, Tee Bulb, or Channel..... }
 Angles on upper edge

5	3	36	5	3	36
---	---	----	---	---	----

Deck. Material and thickness

2 1/2 W.P.