

...OR EXAMINATION AS PER RULE, FOR Condition - confirmation...
...has in dry dock bottom - rudder, cleaned

25-4 TELEGRAFICO: "REGISTER."

ler

25-6-7

-21

Do. 3920

Do.



TELEFONO: No. 23-55.

Lloyd's Register of Shipping.

Enclosures.

Via della Borsa No. 2,

Trieste (II), 18th July 1923.

Ans. 27/7/23

DIPAL SURVEYOR:
G. TURNBULL.

IP SURVEYORS:
C. DYKES.
OSTANTINI, B.Sc.

ENGINEER SURVEYORS:
O. COMMON.
STUPARICH.
BONIVENTO.

Dear Sir,

We are forwarding herewith Report No. 5889 on the steamer "LODOLETTA" and have to inform you that, as the question of fees has not yet been settled in this case, the same will be dealt with in due course.

I am, Dear Sir,


Yours faithfully,

Geo. Fox

For the Surveyors.

The Secretary,

LONDON.



© 2021

Lloyd's Register
Foundation

Committee's Minute.

FRI JUL 27 1923

acter Assigned

See J.E. Rut Jui 5/11/23

Items:-

Copper (Sails) When

Boats...

Masts,

Condition

(State

Sails...

Equipmen

Anchor,

Cables (S

„ leng

„ Bul

Hawser &

Standing &

essel in the R

remain as

1. "W

ay 7.