

sent to Chief Surveyors 16. 3. 23.

Received from Chief Surveyors

VESSEL'S NAME *Stt. Ss. Lodoletta*

Report *haps*

No. *2045*

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Signature of Surveyor

When due

*This vessel was submitted for classification in August 1922 but as the screw shaft did not comply with the Rules, action was deferred until a smaller propeller was fitted or the screw shaft fitted with a continuous link.*

*The Owners state that this will be attended to on the occasion of the next dry docking.*

*Its submitted action be deferred.*



*Wd* © 2021

*17/3/23*

Lloyd's Register Foundation

009376001386-0055

00111-0-1386-0056

1923