

S.S. "LODOLETTA".

A propeller 95" diameter instead of 81" diameter has been fitted to this vessel and the screw shaft only meets the requirements of the Rules for a propeller of the latter diameter

It is submitted by the Chief Engineer Surveyors that the classification of the vessel should be deferred. (See fuller endorsement attached.)



© 2021

Lloyd's Register
Foundation

004376-004386-0000