

LONDON
COPY
J 4.9

Lloyd's Register of Shipping

(CLASSIFICATION SOCIETY RECOGNISED BY THE JAPANESE GOVERNMENT)

No. 5.1

船 舶 満 載 吃 水 線 證 書

COPY

船名	鋼單暗車發動機船	船本番號	
種類	ふろんびあん	船籍港	東京
所有者	三菱商事株式會社		
船ノ長ノ中央ニ於ケル上甲板東側板上面ノ延長ト外板ノ外面トノ交點ヨリ乾舷甲板ヲ標示スル水平線ノ上縁ニ至ル垂直距離	方へ	〇・〇	吋
乾舷甲板ヲ標示スル水平線ノ上縁ヨリ	下方へ	七八	吋
圓標ノ中心ニ至ル垂直距離	上方へ	六	吋
圓標ノ中心ヨリ淡水滿載吃水線ニ至ル垂直距離	上方へ	五・八	吋
圓標ノ中心ヨリ熱帶滿載吃水線ニ至ル垂直距離	上方へ	五・八	吋
圓標ノ中心ヨリ冬期滿載吃水線ニ至ル垂直距離	下方へ	五・八	吋
圓標ノ中心ヨリ冬期北大西洋滿載吃水線ニ至ル垂直距離	下方へ		吋
前記ノ事項ハ何レモ正確ニシテ船舶滿載吃水線法ニ適合スルコトヲ證明ス本證書ハ船舶滿載吃水線法ニ依リ前記ノ事項ヲ變更スルノ必要ヲ生シタルトキ其ノ效力ヲ失フ			
昭和貳年七月貳拾五日			
日本駐在主任検査員			
ロイド船級協會代表者			
勝田銀太郎			

Certificate of the Ship Load Line

COPY

Official Number of the Vessel	Port of Registry	Tokio
Kind and Name of the Vessel	Owner	Steel Single Screw Motor Vessel "Columbia Maru" Mitsubishi Shoji Kaisha, Ltd.
Vertical distance from the point of intersection of the extended line of the upper surface of the stringer plate of the upper deck at mid-length of vessel with the outside of shell-plating, to the upper edge of the horizontal line indicating the Freeboard Deck.		0.0 inches measured ward
Vertical distance from the upper edge of the horizontal line indicating the Freeboard Deck to the Centre of the Disc		18.3 inches measured downward
Vertical distance from the Centre of the Disc to the Fresh Water Load Line		6.4 inches measured upward
Vertical distance from the Centre of the Disc to the Tropical Load Line		5.8 inches measured upward
Vertical distance from the Centre of the Disc to the Winter Load Line		5.8 inches measured downward
Vertical distance from the Centre of the Disc to the Winter North Atlantic Load Line		inches measured downward
It is hereby certified that the above mentioned particulars are correct and in accordance with the Ship Load Line Law.		
This certificate is issued under the conditions noted on the back hereof, and shall become void when it is necessary to alter the above mentioned particulars in accordance with the Ship Load Line Law.		
Principal Surveyor for Japan	For Lloyd's Register of Shipping	
The 25th day of the 7th month of the 2nd year of Taisho. (25th July 1913.)		

checked
W.D.
20.8.27

本證明書發行條件

- 一、ロイド船級協會ニテ等級ヲ附セラレタル船舶、本船ノ等級ヲ變更シ或ハ撤回シタル場合ニハ直ニ本證明書ハ取消サル可ク其手續トシテ本證明書ヲ本協會ニ返附スベシ而シテ船主、船主管理者、船舶借主或ハ船長ハ其際新規證明書請求申込ヲナスベシ。
- 二、ロイド船級協會ニテ等級ヲ附セザル船舶、本證明書ハ年々月日迄有效ニシテ右日付以後ハ其效力消滅ス從テ證明書取消ノ爲メ本證明書ヲ本協會ニ返附スベシ而シテ船主、船主管理者、船舶借主或ハ船長ハ其際新規證明書請求申込ヲナスベシ。
- 三、本證明書紛失或ハ破滅シタル場合ニハ船主、船主管理者、船舶借主或ハ船長ハ遲滞ナク其理由ヲ告知シ本協會ニ證明書再發行ヲ申請スベシ。
- 四、本證明書面記載ノ事項ニ抵触スル變更ヲ行ヒタル時ハ船主、船主管理者、船舶借主或ハ船長ハ遲滞ナク本協會ニ其變更事項ニ關スル告知ヲナシ必要ニ應ジ新規證明書或ハ再査定ヲ申請スベシ。
- 五、本協會ニ新規證明書或ハ再査定ノ申請ヲナス時ハ本證明書ヲ申請書ニ添ヘテ返還スベシ。
- 六、本船ガ損失、沈没或ハ破壞シタル場合或ハ滿載吃水線標ノ必要ナキニ至リタル場合ハ船主、船主管理者、船舶借主或ハ船長ハ遲滞ナク本協會ニ告知シ本證明書ヲ返還スベシ或ハ返還スルコト能ハザル理由ヲ通告スベシ。

Conditions under which this certificate is issued.

1. For vessels classed in Lloyd's Register of Shipping:—
If and so soon as the class of this vessel is either changed or withdrawn this Certificate will be cancelled and must be delivered to the Society for that purpose and the Owner, Agents, Charterer, or Master, must then apply for a new Certificate.
2. For vessels not classed in Lloyd's Register of Shipping:—
This Certificate is valid until the day of 19..... after which date it will cease to have effect and must be delivered to the Society to be cancelled, and the Owner, Agent, Charterer, or Master, must then apply for a new Certificate.
3. If this Certificate is lost or destroyed, the Owner, Agent, Charterer, or Master must, without delay, notify the cause, and request its re-issue by the Society.
4. When any alterations are made affecting the particulars mentioned on this certificate the Owner, Agent, Charterer or Master must, without delay, notify the Society in regard to such alterations, and request a new certificate, or re-assignment as may be necessary.
5. When an application is made to the Society for a new Certificate or for a re-assignment, the original Certificate must be returned with such application.
6. If this vessel is lost, sunk, or broken up or no longer requires a Load Line mark, the Owner, Agent, Charterer, or Master must, without delay, notify the Society and return this certificate or state the reason for not doing so.



© 2021

Lloyd's Register
Foundation