

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of LONDON

No. in Reg. Book Survey held at Date, First Survey Last Survey 19

on the Wood, Iron or Steel M.V. "CALTANURA" (No. of Visits)

YEAR MONTH

When 1938 7

By whom Parkedgemon & Co. Ltd.

Owners' Address

(if not already recorded in Appendix to Register Book).

Port belonging to All Mohar

Managers

Built at Parkedgemon & Co. Ltd.

Owners California Arabian Standard

Managers

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER.

* for Special Survey.

Date of last Survey and of Periodical Surveys.

Machinery and Boiler Surveys (Including date of N.B., if any).

9A

For towing service

in the Persian Gulf

738

S.M.C. 738

Vet Eng.

Change 75

Society's Freeboard (if assigned) as

painted on Ship and now verified

ft. ins.

Was a damage report made by anyone else? if so, by whom?

IRS, OR EXAMINATION AS PER RULE, FOR

RY OF DAMAGE REPAIRS :—

	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

ST CONDITION OF THE

of Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Fastenings	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Fell.)
Plating	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
in way of sidelights	Rudder	Scuppers	Boats
Frames	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
inals	Windlass	Hatches	Condition, how ascertained
ses	Have pumps been examined and found efficient?	Planking	(State if wedges removed.)
Have Sluice Valves been examined and found efficient?	Have Watertight Doors been examined and found efficient?	Caulking	Equipment letter
Have Ventilators and their Coamings been examined and found efficient?	Air and Sounding Pipes	Treenails	Anchors, No. of
Tanks been examined internally?	Doubling Plates under Sounding Pipes	Breasthooks & Stems	Cables (State if now ranged)
Tanks been tested?		Transoms, Pointers & Crutches	length mean diamr.
		Timbers of Frame at openings	(on board)
		Stringers, Clamps & Shelves	Rule length size
		Salting	Chain Locker
		(State if examined.)	Hawsers & Warps
			Standing and Running Rigging
			Sails

eral Observations, Opinion as to Class, Recommendation, &c. :—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

er Section 20)

or Repair Fee (if any)

nses (if chargeable)

Fee (if any)

Fees applied for,

19

Received by me,

19

Minute

er Assigned


Leads

Homo

3 SEP 1941

draw class & insert (...) in repairs

Surveyor to Lloyd's Register of Shipping.



© 2021

Lloyd's Register Foundation

009409-009417-0304