

28 DEC 1944

Lis. No 3941.

"CABO JUBY"

The vessel's class is subject to a stream anchor being supplied at the first opportunity.

When the case received the consideration of the Committee on the 20th ultimo action was deferred for the 3rd S.S. No.3 due 6.44 which ~~was~~ proposed to be carried out at the dry docking and boiler cleaning.

The LISBON Surveyor reports (11.44) this vessel placed in dry dock and an examination made of the decks, ventilators, casings, steering gear, machinery space and bunkers etc.

The wood sheathing over fish hold was found to be in generally bad condition, the frames and stringers in the machinery space and bunkers badly wasted, bulkhead plating between bunker and fish hold generally thin and only 1 bower anchor and 3 lengths of chain cable on board.

The Owners state that the vessel could not be stopped for Survey and repairs until June next and in view of her condition the Surveyor recommends that the class be ~~suspended~~ ~~expunged~~ until the Survey and repairs have been carried out.

The case is submitted for the consideration of the Committee with the suggestion that the character be expunged with a black line on account of reported defects.



© 2011

28.12.44.

Lloyd's Register
Foundation