

5c.17.

now "Cabo Feby"

F.E.

Received by Chief Ship Surveyor 4-1-08

Received from Chief Ship Surveyor

VESSEL'S NAME Ste. Steam Trawler "Ethel" Rpt. Hull No. 19674

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	8/16" in lieu of 8/20"	Not required.
Spar Sheerstrake . .	✓	✓
Description of Framing:— Ordinary, increased in size to compensate (viz., ordinary, deep, zed, channel or bulb-angle). for omission of reserve frames.		

The following repairs are reported to have been done due to collision. — Stern & 6 plates removed. 4 plates, 2 frames and 1 floor fixed in place, 1 breathhole removed. Cement made good, a new 1st anchor and 30 fathoms of chain cable of proper weight, size and test supplied, and minor repairs. See bundle report No. 7318 attached.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed † 100 A 1 ("Steel") "Steam Trawler" as recommended.

† 100 A 1 ("Steel") "Steam Trawler"  
1 Str.

BK 7 1/2" 3BH Can. Dwp. A9CP Q76 F22'



© 2008  
4/1/08

Lloyd's Register Foundation

009409-009417-0329